

The X50Pro Official Firmware Release Note (R1789)

- ① Release date : 28th of April, 2023
- ② The version of updated firmware : R1789
- ③ Refer to the below for the contents updated from R1783 to R1789

A. New Functions

B. Improvement

- 1 Cleared the bug that, deleting just one track from the Music DB list deletes the entire album of that track, and the bug that, deleting individual track in the 'My Music' folder from the Music DB list deletes the entire Music DB.
- 2 Improved the issue that the message 'Now DB Checking' message appears on the screen every time the device boots
- 3 Improved the problem that, after selecting all the folders(albums) using the 'Select All' menu and executing 'Scan Music DB', the message 'The album is already scanned' is displayed and the scan does not work normally. Now that it has been improved, you will see a improved message of 'Check the already scanned folder and remove it from the selected folders please'
- 4 Improved that Amazon cover art service should work again.
- 5 Improved the issue that the device automatically powers off after 20 minutes when Airplay is executed with ERP set to 'On' in setup
- 6 Improve not to ask for confirmation twice when 'Copy' or 'Move' function is executed.
- 7 When executing the Copy(Move) function, there is a function that asks if you want to scan the file copied(moved) in the last step. If you copy(move) to the 'My Music' folder, it is automatically scanned, so it has been improved so that you will not be asked whether you want to scan the copied(moved) file.
- 8 The code related to Qobuz streaming service has been fine-tuned so that the Qobuz streaming service works stably
- 9 Improved that Gracenote cover art service should work.

Thank you very much!